



Date: 16 January, 2009

Location: Interior Cheshire.

General Comments: At 1520 the Cutterhead pinion gear was compromised from seal failure from fishing line- over the weekend it will be replaced.

Events: 0730: Started dredge
1520: Stopped dredge

Turbidity Monitoring: 1000: 15.0 NTU
1200: 15.5 NTU
1400: 15.9 NTU
1525: 16.1 NTU

Percent Complete: 78 % Interior Cheshire

Problems: None

Tomorrow: Moving forward with Interior Cheshire.